

AD-A154 501

NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS
LOWER PORTER POND DAM. (U) CORPS OF ENGINEERS WALTHAM
MA NEW ENGLAND DIV JAN 80

1/1

UNCLASSIFIED


F/G 13/13

NL

END

FILM 13

211



NATIONAL BUREAU OF STANDARDS
MICROCOPY RESOLUTION TEST CHART

AD-A154 501

TAUNTON RIVER BASIN
BROCKTON, MASSACHUSETTS

LOWER PORTER POND DAM
MA 00424

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM

DTIC FILE COPY



DTIC
ELECTE
JUN 3 1985
S D E

DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
WALTHAM, MASS. 02154

This document has been approved
for public release and sale; its
distribution is unlimited.

JANUARY 1980

Original contains color
plates: All DTIC reproductions
will be in black and
white.

85 5 20 103

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ADA 154 501

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER MA 00424	2. GOVT ACCESSION NO	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Lower Porter Pond Dam NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE January 1980
		13. NUMBER OF PAGES 48
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report) "Original contains color plates: All DTIC reproduct- ions will be in black and white"		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Taunton River Basin Brockton, Massachusetts Beaver Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) Lower Porter Dam is an ill- defined earth embankment about 200 ft. long with a maximum height of about 12 ft. and a top width averaging 15 ft. The dam appears to be in fair condition. With a classification size of small and a hazard potential of significant, the recommended range for test flood is $\frac{1}{2}$ og the Probable Maximum Flood. The owner should implement various operat' al and maintenance procedures.		



DEPARTMENT OF THE ARMY
NEW ENGLAND DIVISION, CORPS OF ENGINEERS
424 TRAPELO ROAD
WALTHAM, MASSACHUSETTS 02154

REPLY TO
ATTENTION OF

NEDED

MAY 19 1990

Honorable Edward J. King
Governor of the Commonwealth of
Massachusetts
State House
Boston, Massachusetts 02133

Dear Governor King:

Inclosed is a copy of the Lower Porter Pond Dam Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Department of Environmental Quality Engineering, the cooperating agency for the Commonwealth of Massachusetts. In addition, a copy of the report has also been furnished the owner, the city of Brockton.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Department of Environmental Quality Engineering for your cooperation in carrying out this program.

Sincerely,

Max B. Scheider
MAX B. SCHEIDER

Colonel, Corps of Engineers
Division Engineer

Incl
As stated

LOWER PORTER POND DAM

MA 00424

TAUNTON RIVER BASIN
BROCKTON, MASSACHUSETTS

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM



Accession For	
NTIS GRA&I	
DTIC TAB	
Unannounced	
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or
AY	Special

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT

Identification No.: MA 00424
Name of Dam: Lower Porter Pond Dam
Town: Brockton
County and State: Plymouth, Massachusetts
Stream: Beaver Brook
Date of Inspection: October 17, 1979

BRIEF ASSESSMENT

Lower Porter Pond Dam is an ill-defined earth embankment approximately 200 feet long with a maximum height of about 12 feet and a top width averaging 15 feet. The upstream slope, which is capped with a 2-foot high parapet wall, is unknown and the downstream slope is about 2H:1V. The broad-crested stone masonry service spillway is located near the right abutment. The broad-crested stone masonry auxiliary spillway is situated about 60 feet to the right of the service spillway. The dam was constructed in 1940 for the City of Brockton park development program and is currently used for recreational purposes.

The dam appears to be in fair condition. Roots of large trees growing on the dam crest may increase the seepage potential and high winds may dislodge the trees removing significant portions of embankment material. The absence of grass cover on a portion of the dam crest exposes the embankment to undesirable surface erosion.


Lower Porter Pond Dam has a maximum storage capacity of approximately 54 acre-feet and a maximum height of about 12 feet. Therefore, the dam is classified in the "Small" size category. Approximately 35 inhabitable structures are located downstream of Thirty Acre Pond, which is located immediately downstream of Lower Porter Pond. A densely populated urban neighborhood is located further downstream. A failure of Lower Porter Pond dam could cause appreciable property damage but little or no loss of life in the downstream communities. Therefore, the dam is classified in the "Significant" hazard category. The recommended range for the test flood for a "Small size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). The selected test flood for this structure is one-half of the PMF.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow.

Within one year after receipt of the Phase I inspection report, the Owner, the City of Brockton, should retain the services of a registered professional engineer, experienced in the design and construction of dams, for the following purposes: (1) detailed hydrologic and hydraulic analyses should be performed to assess the need for increasing the project discharge capacity; and (2) a study should be made to examine the possibility of Waldo Lake (upstream of Lower and Upper Porter Pond) overflowing the area along the D.W. Field East Parkway and to evaluate the consequences of such an occurrence; (3) the trees and their root systems should be removed from the embankment to the extent possible and the voids in the embankment backfilled with appropriate compacted embankment materials; and (4) the seismic stability of the dam should be investigated.

In addition, the Owner should implement the following operational and maintenance procedures: (1) the bare spots on the embankment crest should be covered with suitable vegetation and protected from pedestrian traffic; (2) erosion protection should be provided for the upstream slope of the embankment; (3) the operating condition of the pond drain sluice gate should be determined and the gate should be repaired if necessary; (4) a program of annual periodic technical inspection should be instituted; and (5) a formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation, should be developed.

O'BRIEN & GERE ENGINEERS, INC.



Date 22 FEB 1980


This Phase I Inspection Report on Lower Porter Pond Dam has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.



RICHARD DIBUONO, MEMBER
Water Control Branch
Engineering Division



ARAMAST MAHTESIAN, MEMBER
Foundation & Materials Branch
Engineering Division



CARNEY M. TERZIAN, CHAIRMAN
Design Branch
Engineering Division

APPROVAL RECOMMENDED:



JOE B. FRYAR
Chief, Engineering Division

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation, and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

The Phase I Investigation does not include an assessment of the need for fences, gates, no-trespassing signs, repairs to existing fences and railings and other items which may be needed to minimize trespass and provide greater security for the facility and safety to the public. An evaluation of the project for compliance with OSHA rules and regulations is also excluded.

TABLE OF CONTENTS

<u>SECTION</u>	<u>PAGE</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

REPORT

1. PROJECT INFORMATION

1.1	General	1-1
	a. Authority	1-1
	b. Purpose of Inspection	1-1
1.2	Description	1-1
	a. Location	1-1
	b. Description of Dam and Appurtenances	1-2
	c. Size Classification	1-2
	d. Hazard Classification	1-2
	e. Ownership	1-2
	f. Operator	1-2
	g. Purpose of Dam	1-3
	h. Design and Construction History	1-3
	i. Normal Operational Procedure	1-3
1.3	Pertinent Data	1-3
	a. Drainage Area	1-3
	b. Discharge at Damsite	1-3
	c. Elevation	1-4
	d. Reservoir	1-4
	e. Storage	1-4
	f. Reservoir Surface	1-4
	g. Dam	1-4
	h. Diversion and Regulating Tunnel	1-5
	i. Spillway	1-5
	j. Regulating Outlets	1-5

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
2. ENGINEERING DATA	
2.1 Design Data	2-1
2.2 Construction	2-1
2.3 Operation	2-1
2.4 Evaluation	2-1
a. Availability	2-1
b. Adequacy	2-1
c. Validity	2-1
3. VISUAL INSPECTION	
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-1
d. Reservoir Area	3-2
e. Downstream Channel	3-2
3.2 Evaluation	3-2
4. OPERATIONAL AND MAINTENANCE PROCEDURES	
4.1 Operational Procedures	4-1
a. General	4-1
b. Description of Any Warning System in Effect	4-1
4.2 Maintenance Procedures	4-1
a. General	4-1
b. Operating Facilities	4-1
4.3 Evaluation	4-1
5. EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES	
5.1 General	5-1
5.2 Design Data	5-1
5.3 Experience Data	5-1
5.4 Test Flood Analysis	5-1
5.5 Dam Failure Analysis	5-2

TABLE OF CONTENTS (Con't)

<u>SECTION</u>	<u>PAGE</u>
6. EVALUATION OF STRUCTURAL STABILITY	
6.1 Visual Observations	6-1
6.2 Design and Construction Data	6-1
6.3 Post-Construction Changes	6-1
6.4 Seismic Stability	6-1
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-2
7.4 Alternatives	7-2

APPENDICES

APPENDIX A - INSPECTION CHECKLIST	A-1 to A-8
APPENDIX B - ENGINEERING DATA	B-1 to B-5
APPENDIX C - PHOTOGRAPHS	C-1 to C-6
APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS	D-1 to D-31
APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS	



AN OVERVIEW OF THE LOWER PORTER POND DAM. (10/17/79)



AN OVERVIEW OF THE LOWER PORTER POND DAM. (10/17/79)

SECTION 7

ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual observations and review of the available information indicate that Lower Porter Pond Dam is in fair condition. The roots of trees growing on the dam crest may increase the seepage potential and high winds may dislodge the trees removing significant portions of embankment material. The absence of grass cover on a portion of the dam crest exposes the embankment to undesirable surface erosion.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow. A failure of the dam would cause a rise in stream elevation of approximately 1.1 feet at the downstream damage area which could result in appreciable property damage but little or no loss of life.

b. Adequacy of Information. The available information together with the visual inspection data are adequate for a Phase I assessment of Lower Porter Pond Dam.

c. Urgency. Further investigations and remedial measures should be implemented within one year of receipt of this Phase I Inspection Report.

7.2 Recommendations

The following recommendations should be implemented by a registered professional engineer experienced in the design and construction of dams.

1) Detailed hydrologic and hydraulic analyses should be performed to assess the necessity for increasing the project discharge capacity.

2) It appears that Waldo Lake, upstream of Lower and Upper Porter Pond, could overflow in the area along the D. W. Field East Parkway prior to overtopping the dam crest. A study should be made to examine this possibility and to evaluate the consequences of such an occurrence.

3) The trees and their root systems should be removed from the embankment to the extent possible and the voids in the embankment replaced with appropriate compacted embankment materials.

4) The seismic stability of the dam should be investigated utilizing conventional equivalent static load methods.

SECTION 6

STRUCTURAL STABILITY

6.1 Visual Observations

The roots of trees growing on the dam crest could provide increased seepage potential through the embankment. High winds could dislodge the trees and their root systems causing significant losses of embankment material. The roots of the deciduous tree growing within two feet of the eastern service spillway training wall may destroy the masonry joint material and cause dislocation of individual stones. The loss of grass cover on the dam crest exposes the embankment to surface erosion which might lead to a reduction of the effective top of dam elevation.

6.2 Design and Construction Data

No information was available concerning stability analyses, seepage computations, or embankment and foundation material properties.

6.3 Post Construction Changes

No post construction changes have been performed at this site.

6.4 Seismic Stability

Lower Porter Pond Dam is located in Seismic Zone 3 on the "Seismic Zone Map of Contiguous States." Therefore, according to the Recommended Guidelines for Safety Inspection of Dams, a seismic stability analysis should be performed as recommended in Section 7.

the east of Waldo Lake, noted in paragraph 5.1, were not included in the routing procedures.

The test flood peak inflow to Lower Porter Pond was computed as 2,510 cfs. The routed test flood outflow of 2,505 cfs overtops the embankment by 1.2 feet. The spillway system is capable of discharging 488 cfs prior to overtopping of the embankment, which is about 19 percent of the routed test flood outflow.

5.5 Dam Failure Analysis

A failure of the embankment was simulated by the HEC-1-DB computer program assuming a 20-foot wide and 7-foot deep breach with vertical side slopes developing within one hour. The failure is assumed to occur with the reservoir surface at the top of dam elevation. The resulting outflow was routed to the damage center, which was assumed to be the community of approximately 35 homes downstream of Thirty Acre Pond. The channel cross-section utilized in the computer program for the hazard area was taken at a point 1,200 feet downstream of Thirty Acre Pond and is shown on page D-12. The increase in stream depth at this location was computed to be 1.1 feet. This depth of flow could cause appreciable property damage and little or no loss of life in the downstream damage center.

SECTION 5

EVALUATION OF HYDRAULIC/HYDROLOGIC FEATURES

5.1 General

Lower Porter Pond Dam has an elongated watershed about 4 miles long and 0.9 miles wide. The drainage area is wooded with some residential developments and low-lying marshes in the upper reaches. The topography ranges from Elev. 250 to Elev. 160 at the normal pool surface. There are three impoundments upstream of Lower Porter Pond: Brockton Reservoir, Waldo Lake and Upper Porter Pond. The normal pool storage capacities of these three impoundments are about 190, 180 and 28 acre-feet, respectively. It was noted during the visual inspection that the area east of Waldo Lake may be lower in elevation than the top of the dam, thus forming a saddle about 2,000 feet long. Therefore, large inflows into Waldo Lake might be diverted over this saddle into the adjacent watershed. This would in turn reduce the impact of the selected test flood upon Lower Porter Pond Dam and its downstream hazard area.

5.2 Design Data

Neither hydraulic nor hydrologic design data are available for Lower Porter Pond Dam.

5.3 Experience Data

There are no records of high reservoir pools or dam overtoppings at this site.

5.4 Test Flood Analysis

The recommended test flood range for a "Small" size, "Significant" hazard dam is from the 100-year flood to one-half of the Probable Maximum Flood (PMF). Due to the potential for property damage and the possibility of loss of life (although remote) in the downstream damage center, the selected test flood is one-half of the PMF.

Hydrologic and hydraulic calculations were performed with the assistance of the HEC-1-DB computer program. The flood hydrographs were constructed from the Snyder unit hydrographs using average coefficients, an initial infiltration of zero and a constant loss rate of 0.05 inches per hour. The Hop Brook Adjustment Factor was used to reduce the Probable Maximum Precipitation based on the drainage area. The routing sequence consisted of dividing the watershed into sub basins for each impoundment and routing the inflow hydrographs through each reservoir. Stage vs. discharge and stage vs. storage relationships above the spillway crest and the top of the dam were developed for all five dams in the system to obtain outflow hydrographs. All impoundments were assumed to be at their respective spillway crest elevations at the beginning of the storm event. Possible overflow effects to

SECTION 4

OPERATIONAL AND MAINTENANCE PROCEDURES

4.1 Operational Procedures

a. General. Based upon information supplied by the City of Brockton and the Massachusetts DEQE, and that obtained through subsequent conversations with Mr. John Dorgan Sr., Park Commissioner, no formal operating procedures have been established for operation of Lower Porter Pond Dam.

b. Description of Any Warning System in Effect. According to Mr. Dorgan, no flood warning system is in effect for Lower Porter Pond Dam.

4.2 Maintenance Procedures

a. General. According to Mr. Dorgan, the grass on the embankment crest is cut on a regular basis during the growing season.

b. Operating Facilities. According to Mr. Dorgan, the outlet conduit sluice gate is operable and no formal maintenance program is in effect at this site.

4.3 Evaluation

There are no operational procedures in effect at this site. Recommendations for improving these conditions are given in Section 7.3.

missing at the time of inspection. The outlet end of this pipe appeared to be free of debris and was partially submerged.

d. Reservoir Area. The area surrounding the pond consists primarily of well-maintained grass areas which slope gradually up from the edge of the pond. Portions of the surrounding area are forested.

e. Downstream Channel. The stilling basin, which accepts discharge from both spillways and the outlet conduit, is lined with hand-placed riprap and is reported to be about four feet deep. There is no evidence of excessive erosion or displacement of the stone lining around the basin. The pool elevation in the basin was the same as that of Thirty Acre Pond at the time of inspection. The parkway bridge openings were clear of debris and the bridge itself appeared to be in good condition.

3.2 Evaluation.

The dam is considered to be in fair condition. Bare spots on the crest of the dam and lack of erosion protection on the upstream slope could lead to surface erosion of the embankment. The roots of the trees growing from the crest create potential seepage paths through the dam. In the event of severe winds uprooting the trees, portions of the embankment could be dislodged. Both spillways appear to be in satisfactory condition.

SECTION 3

VISUAL INSPECTION

3.1 Findings

a. General. The field inspection of Lower Porter Pond Dam was performed on October 17, 1979. At the time of the inspection, the reservoir water surface was about 2 inches above the spillway crest. No underwater areas were inspected.

The observations and comments of the field inspection team are in the checklist which is Appendix A of this report.

b. Dam. The dam is considered to be in fair overall condition. The visible portions of the upstream slope below reservoir level appear to grade very gently away from the spillway wingwalls and the vertical stone wall curbing. There is no evidence of riprap on the submerged slope. The masonry wingwalls and parapet wall appear to be in good condition. The embankment crest width varies from 15 to 20 feet and is grass covered. Bare earth is exposed parallel to the eastern service spillway training wall (see overview photo). It was observed that the left abutment area extends to the east of the embankment for a distance of at least 300 feet with the same elevation as the dam crest. A deciduous tree about forty feet tall and two smaller evergreens are growing on the dam crest. The downstream slope supports shrubs and flowers planted as part of a park beautification program. There was no evidence of seepage on the date of the inspection.

c. Appurtenant Structures. The broad-crested masonry service spillway located at the right abutment appears to be in fair condition. The masonry walls of the approach channel have a slope of 1H:1V and show little evidence of deterioration. The center five feet of the masonry weir crest is depressed about 3 inches below the remaining length of weir. It could not be determined if this section was constructed in this manner or if there is settlement of the spillway headwall.

The broad-crested auxiliary spillway is located about 60 feet northwest of the service spillway. The weir crest is composed of non-mortared loose stone and has a non-uniform surface elevation. The vertical non-mortared training walls are in good condition. It was noted that discharge was flowing between the large cobbles forming the downstream end of the weir crest. The downstream channel invert is less than one foot below the poorly defined weir crest and is composed of the same cobble size material. A low-lying area west of the auxiliary spillway appears to function as a stilling pool during high spillway discharges. The unlined outlet channel downstream of the stilling pool is trapezoidal in section and contains three one foot drops of non-mortared stone construction. Undermining of the left side of the outlet channel has created a vertical side wall about 3 feet high.

A 30-inch diameter pre-cast concrete outlet pipe is located about 10 feet west of the service spillway. The sluice gate is submerged and the operator was

SECTION 2

ENGINEERING DATA

2.1 Design

The following information was made available for review of Lower Porter Pond Dam:

1. Report entitled "Master Plan Study for D. W. Field Park," April 1968 prepared by Camp, Dresser and McKee, Boston, Massachusetts.
2. Dam inspection report prepared by Commonwealth of Massachusetts, Department of Environmental Quality and Engineering (DEQE), December, 1972.
3. Dam inspection report prepared by the County of Plymouth, Engineering Department, February, 1942.
4. Drawing entitled "Proposed Location and Design for Permanent Structures at Easton Dam" dated April, 1940.

Note 1: No design calculations, embankment cross-sections, or record drawings are available for this site.

Note 2: The principal design features for this dam are shown on the sketches enclosed in Appendix B.

2.2 Construction

No information is available concerning construction of Lower Porter Pond Dam except that it was part of the Works Progress Administration program in 1940.

2.3 Operation

No operational data is available for this site.

2.4 Evaluation

a. Availability. The information made available was obtained from the City of Brockton and the DEQE.

b. Adequacy. The drawing and reports together with the visual inspection data are adequate for a Phase I Investigation.

c. Validity. The data obtained for this site is in general conformance with the field measurements.

h. Diversion and Regulating Tunnel.

Not applicable.

i. Spillway.

Type (Service)	Broad-crested masonry weir
(Auxiliary)	Broad-crested loose stone weir
Length (Service)	12 feet
(Auxiliary)	20 feet
Crest Elevation (Service)	160.0
(Auxiliary)	160.0
Gates	None
Upstream Channel (Service)	11 feet long, masonry invert 12 feet wide, grouted stone side-slopes.
(Auxiliary)	None
Downstream Channel (Service)	Stilling basin & Thirty Acre Pond
(Auxiliary)	Stilling pool, trapezoidal drop sections, stilling basin & Thirty Acre Pond.

j. Regulating Outlets. A hand-operated sluice gate of unknown dimensions is situated at the upstream end of a 30 inch diameter pre-cast concrete outlet pipe. The gate invert elevation is approximately 154.0 MSL and is considered to be at or near the bottom of Lower Porter Pond.

c. Elevation. (feet above NGVD)

Streambed at Toe of Dam	151.0
Bottom of Cutoff	NA
Maximum Tailwater	158+
Normal Pool	160.0
Full Flood Control Pool	NA
Spillway Crest (Service and Auxiliary)	160.0
Design Surcharge (Original Design)	Unknown
Top of Dam	163.0
Test Flood Pool Design Surcharge	164.2

d. Reservoir. (Length in feet)

Normal Pool	900
Flood Control Pool	NA
Spillway Crest Pool	900
Top of Dam	920
Test Flood Pool	950

e. Storage. (Acre-feet)

Normal Pool	24
Flood Control Pool	NA
Spillway Crest Pool	24
Top of Dam	54
Test Flood Pool	69

f. Reservoir Surface. (Acres)

Normal Pool	8
Flood Control Pool	NA
Spillway Crest	8
Top of Dam	12
Test Flood Pool	14

g. Dam.

Type	Earth embankment
Length	200 feet
Height	12 feet
Top Width	15-20 feet
Side Slopes (upstream)	Unknown earth slope below the water capped with a parapet wall.
(downstream)	2H:1V
Zoning	Unknown
Impervious Core	Unknown
Cutoff	Unknown
Grout Curtain	Unknown

g. Purpose of Dam. The dam was constructed and is presently used for recreational purposes.

h. Design and Construction History. Lower Porter Pond Dam, originally called Easton Dam, was constructed in 1940 as part of the Works Projects Administration (WPA) program. Further information is unavailable.

i. Normal Operating Procedures. The reservoir is normally self-regulating with the normal pool slightly above the crest elevation of the service and auxiliary spillways.

1.3 Pertinent Data

a. Drainage Area. The watershed for Lower Porter Pond Dam is approximately 3.4 square miles in area and is wooded with some residential developments and low-lying marshes in the upper reaches. Three reservoirs (Brockton Reservoir, Waldo Lake, and Upper Porter Pond) are located upstream of Lower Porter Pond within the drainage area.

b. Discharge at Damsite.

1) Outlet Works. The outlet works consists of a gated 30-inch diameter pre-cast concrete pipe with an invert elevation of 154.0 MSL. The estimated discharge capacity is about 25 cfs when the reservoir surface is at the top of the dam.

2) Maximum Known Flood at Damsite. Unknown.

3) Ungated Spillway Capacity at Top of Dam. The combined discharge capacity of the service and auxiliary spillways with reservoir at top of dam Elev. 163.0 is 488 cfs.

4) Ungated Spillway Capacity at Test Flood Elevation. The combined spillway capacity with reservoir at test flood Elev. 164.2 is about 720 cfs.

5) Gated Spillway Capacity at Normal Pool. Not applicable.

6) Gated Spillway capacity at Test Flood Elevation. Not applicable.

7) Total Spillway Capacity at Test Flood Elevation. Same as 4) above.

8) Total Project Discharge at Top of Dam. Same as 3) above.

9) Total Project Discharge at Test Flood. The combined discharge capacity of the spillways and the flow over the dam at test flood Elev. 164.2 is 2,500 cfs.

b. Description of Dam and Appurtenances. Lower Porter Pond Dam is an ill-defined earth embankment approximately 200 feet long with a maximum height of about 12 feet. The top width is approximately 15 feet and the downstream slope is about 2H:1V. The upstream slope is unknown and is capped with a two-foot high parapet wall.

The broad-crested stone masonry service spillway is located near the right abutment. The trapezoidal approach apron is eleven feet long and consists of a masonry invert with grouted stone side slopes. The spillway has a 12-foot long weir and a 9-foot high vertical downstream headwall. Discharge over the service spillway is directed into a riprapped stilling basin and then into Thirty Acre Pond through a double arch reinforced concrete highway bridge. Each arch has a clear opening about 10 feet wide and 7 feet high.

The broad-crested stone masonry auxiliary spillway is situated about 60 feet to the right of the service spillway. The spillway is 20 feet long with vertical masonry training walls and a dumped rock invert. The initial outlet channel elevation is about one foot below the weir crest. The channel slopes gently downstream and outlets into a shallow stilling pool. The channel is constructed downstream of the stilling pool as a series of trapezoidal drop sections for a distance of approximately 50 feet where discharges from the auxiliary spillway are conveyed into the service spillway stilling basin.

c. Size Classification. Lower Porter Pond Dam has a maximum storage capacity of approximately 54 acre-feet and a maximum height of about 12 feet. The criteria for the "Small" size category includes dams which have less than 1,000 acre-feet storage capacity and are less than 40 feet high. Lower Porter Pond Dam is therefore classified as a "Small" size dam.

d. Hazard Classification. Lower Porter Pond Dam is located approximately 70 feet upstream of Thirty Acre Pond. Approximately 35 single family dwellings and commercial establishments are downstream of Thirty Acre Pond. In addition, the discharge from Thirty Acre Pond passes through two small ponds, a narrow man-made channel approximately one mile long and into a 1,800-foot long underground culvert. The region of potential flooding which borders the man-made channel and which is upstream of the culvert is a densely populated urban neighborhood. The dam is classified as "Significant" hazard since flood waters resulting from failure at Lower Porter Pond Dam could cause appreciable property damage but little or no loss of life. This assessment is based on the breach analysis, which computed a stream depth of 1.1 feet at the initial downstream damage center.

e. Ownership. The dam is owned by the City of Brockton, Department of Parks and Recreation, City Hall, Brockton, Massachusetts, 02401, Telephone 617-580-1100.

f. Operator. The dam is operated by the Department of Parks and Recreation. Mr. John Dorgan Sr., Park Commissioner, is in charge of dam operations. Telephone 617-580-1100.

NATIONAL DAM INSPECTION PROGRAM
PHASE I INSPECTION REPORT
LOWER PORTER POND DAM

SECTION 1

PROJECT INFORMATION

1.1 General


a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspections throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. O'Brien & Gere Engineers, Inc. has been retained by the New England Division to inspect and report on selected dams in the Commonwealth of Massachusetts. Authorization and notice to proceed were issued to O'Brien & Gere Engineers, Inc. by a letter from the Corps of Engineers dated November 6, 1979 and signed by Colonel William E. Hodgson, Jr. Contract No. DACW33-80-C-0014 has been assigned by the Corps of Engineers for this work.

b. Purpose. The purpose of performing technical inspection and evaluation of non-federal dams is to:

1. Identify conditions which threaten public safety and make the Owner aware of any deficiencies to permit him to correct them in a timely manner.
2. Encourage and prepare the states to initiate effective dam safety programs for non-federal dams.
3. Update, verify, and complete the National Inventory of Dams.

1.2 Description of Project (Information for this dam was obtained from the City of Brockton and the Massachusetts Department of Environmental Quality and Engineering (DEQE).

a. Location. Lower Porter Pond Dam is located on Beaver Brook within the City of Brockton, Massachusetts. A 35-home community located about 0.5 miles downstream is considered the major damage center. Beaver Brook outlets into Salisbury Brook about 0.75 miles downstream and Salisbury Brook joins Trout Brook to form the Salisbury Plain River about 2 miles downstream of the dam. The dam is shown on the USGS Quadrangle entitled "Brockton, Massachusetts" at coordinates N 42° 05.9', W 71° 02.6'. A regional location plan of Lower Porter Pond Dam is enclosed as Figure 1, pg. vi.



7.3 Remedial Measures

- 1) The bare spots on the embankment crest should be covered with suitable vegetation and protected from pedestrian traffic.
- 2) Erosion protection should be provided for the upstream slope of the embankment.
- 3) The operating condition of the pond drain sluice gate should be determined and the gate should be repaired, if necessary. The gate operator should be stored in a convenient location for emergency use.
- 4) A program of annual periodic technical inspection should be instituted.
- 5) A formal surveillance and flood warning plan, including round-the-clock monitoring during heavy precipitation, should be developed.

7.4 Alternatives

As an alternative to the above recommendations and remedial measures, the dam could be breached and the pond drained.

APPENDIX A

INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST

INSPECTION TEAM ORGANIZATION

Project: LOWER PORTER POND DAM
National I.D. #: MA 00424
Location: Brockton, MA
Type of Dam: Earth Embankment
Inspection Date(s): October 17, 1979
Weather: Overcast, 47°
Pool Elevation: 160.2 MSL

Inspection Team

Leonard Beck	O'Brien & Gere	Structures
Steven Snider	O'Brien & Gere	Foundations & Materials
Alan Hanscom	O'Brien & Gere	Structures
Rodney Georges	Bryant & Associates	Hydrology/Hydraulics

*Mr. John J. Williams, Vice-President, O'Brien & Gere has visited the site but not necessarily in conjunction with the inspection team.

Owner's Representative

Mr. John Dorgan, Park Commissioner, D.W. FIELD PARK
Brockton MA

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAMNational I.D. #: MA 00424Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT</u>	
Crest Elevation	160.0 MSL
Current Pool Elevation	160.2 MSL
Maximum Impoundment to Date	Unknown.
Surface Cracks	None.
Pavement Condition	N/A
Movement or Settlement of Crest	None.
Lateral Movement	None.
Vertical Alignment	Good.
Horizontal Alignment	Good.
Condition at Abutment and at Concrete Structures	No problems noted.
Indications of Movements of Structural Items on Slopes	None.
Trespassing on Slopes	Bare ground on embankment crest near spillway.
Vegetation on Slopes	Flowers and small shrubs on d/s slope; part of beautification prog.
Sloughing or Erosion of Slopes or Abutments	None.
Rock Slope Protection - Riprap Failures	None.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>DAM EMBANKMENT (Con't)</u>	
Unusual Movement or Cracking at or near Toes	<i>None.</i>
Unusual Embankment or Downstream Seepage	<i>None.</i>
Piping or Boils	<i>None.</i>
Foundation Drainage Features	<i>None.</i>
Toe Drains	<i>None.</i>
Instrumentation System	<i>None.</i>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<p>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS <u>SERVICE SPILLWAY</u></p> <p>a. Approach Channel</p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p> <p>c. Discharge Channel</p> <p>General Condition</p>	<p><i>Fair.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>Grouted stones in good condition.</i></p> <p><i>Depression in stone masonry spillway head wall.</i></p> <p><i>N/A.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>Good. Riprapped stilling basin & Thirty Acre Pond.</i></p>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Con't)	
<u>SERVICE SPILLWAY</u>	
Loose Rock Overhanging Channel	None.
Trees Overhanging Channel	None.
Floor of Channel	Unknown. Submerged.
Other Obstructions	R/C double arch bridge about 45' d/s of Service Spillway.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<p>OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS <u>AUXILIARY SPILLWAY</u></p> <p>a. Approach Channel</p> <p>General Condition</p> <p>Loose Rock Overhanging Channel</p> <p>Trees Overhanging Channel</p> <p>Floor of Approach Channel</p> <p>b. Weir and Training Walls</p> <p>General Condition of Concrete</p> <p>Rust or Staining</p> <p>Spalling</p> <p>Any Visible Reinforcing</p> <p>Any Seepage or Efflorescence</p> <p>Drain Holes</p> <p>c. Discharge Channel</p> <p>General Condition</p>	<p><i>Poor.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>Dumped stone.</i></p> <p><i>Vertical stone masonry walls in good condition. Irregular stone crest.</i></p> <p><i>None.</i></p> <p><i>Some loss of mortar.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>None.</i></p> <p><i>Fair. Some erosion of left channel bank.</i></p>

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
OUTLET WORKS - SPILLWAY WEIR, APPROACH AND DISCHARGE CHANNELS (Con't)	
Loose Rock Overhanging Channel	Some at bank under mining.
Trees Overhanging Channel	One deciduous tree at location of undermining.
Floor of Channel	Dumped stone w/ three stone masonry steps.
Other Obstructions	None.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE</u>	
a. Approach Channel	
Slope Conditions	Submerged.
Bottom Conditions	Submerged.
Rock Slides or Falls	None.
Log Boom	N/A
Debris	None.
Condition of Concrete Lining	Unknown.
Drains or Weep Holes	None.
b. Intake Structure - <u>OPEN AIR GATE VALVE</u>	
Condition of Concrete	Masonry headwall in good condition.
Stop Logs and Slots	None.
Sluice Gate	Operator missing. Unknown if operable according to owner's representative.

VISUAL INSPECTION CHECK LIST

Project: LOWER PORTER POND DAM

National I.D. #: MA 00425

Date(s): October 17, 1979

AREA EVALUATED	CONDITIONS
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	N/A
Rust or Staining on Concrete	N/A
Spalling	N/A
Erosion or Cavitation	None.
Cracking	None.
Alignment of Monoliths	N/A
Alignment of Joints	N/A
Numbering of Monoliths	N/A
Condition of Outlet Conduit	PCCP outlet in good condition. Partially submerged by stilling basin.

APPENDIX B

ENGINEERING DATA

LOWER PORTER POND DAM

SHEET

BY

DATE


JOB NO.

APPENDIX B


ENGINEERING DATA

TABLE OF CONTENTS


	<u>PAGE</u>
<i>SITE PLAN & SPILLWAY SECTIONS</i>	<i>B-1</i>
<i>BROCKTON RESERVOIR DAM SYSTEM</i>	<i>B-2</i>
<i>DESCRIPTION OF DAM (DEQE FILES)</i>	<i>B-3</i>
<i>INSPECTION OF DAM & RESERVOIR, PLYMOUTH CO. (DEQE FILES)</i>	<i>B-4</i>
<i>SPILLWAY PICTURES (DEQE FILES)</i>	<i>B-5</i>



SERVICE SPILLWAY SECTION



AUXILIARY SPILLWAY SECTION



Thirty Acre Pond
WSE 154.0 MSL

U S ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	
Contract No. DACW 33-80-C-0014 LOWER PORTER POND DAM	
SITE PLAN & SPILLWAY SECTIONS	
DATE JANUARY 1980	SCALE NONE
OBRIEN & GORE	
8 - 1	




11. TYPICAL REACH OF SALISBURY BROOK ABOUT 1½ MILES DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)



12. ENTRANCE TO APPROXIMATELY 600 YARD LONG BOX CULVERT FOR SALISBURY BROOK IN BROCKTON ABOUT ONE AND 3/4 MILES DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)



9. E. BRETT POND (DRAINED) INLET STRUCTURE ABOUT 1150 YARDS DOWN-
STREAM OF LOWER PORTER POND DAM. (10/17/79)



10. CROSS POND SPILLWAY APPROXIMATELY 1450 YARDS DOWNSTREAM OF LOWER
PORTER POND DAM. (10/17/79)



7. UPPER PORTER POND DAM SPILLWAY APPROXIMATELY 350 YARDS UPSTREAM OF LOWER PORTER POND DAM. (10/17/79)




8. 30 ACRE POND DAM SPILLWAY ABOUT 700 YARDS DOWNSTREAM OF LOWER PORTER POND DAM. (10/17/79)



5. BROCKTON RESERVOIR DAM SPILLWAY APPROXIMATELY 2100 YARDS UP-
STREAM OF LOWER PORTER POND DAM. (10/17/79)



6. WALDO LAKE DAM SPILLWAY ABOUT 1050 YARDS UPSTREAM OF LOWER PORTER
POND DAM. (10/17/79)



3. BRIDGE APPROXIMATELY 50 FEET DOWNSTREAM OF THE SERVICE SPILLWAY
AND 150 FEET DOWNSTREAM OF THE AUXILARY SPILLWAY. (10/17/79)




4. CHANNEL DOWNSTREAM OF THE BRIDGE WHICH IS DOWNSTREAM OF THE
IMPOUNDMENT. (10/17/79)




1. SERVICE SPILLWAY LOOKING UPSTREAM TOWARD THE IMPOUNDMENT.
(10/17/79)



2. AUXILARY SPILLWAY OUTLET CHANNEL LOOKING DOWNSTREAM. (10/17/79)





U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION	
Contract No. DACW 33-80-C-0014	
LOWER PORTER POND DAM	
SITE PLAN & SPILLWAY SECTIONS	
DORRIS GORE	DATE: JANUARY 1980
	SCALE: NONE
A	

APPENDIX C
SELECTED PHOTOGRAPHS OF PROJECT

<u>LOCATION PLAN</u>	<u>Page</u> <u>No.</u>
----------------------	---------------------------

Site Plan Sketch	A
------------------	---

Regional Plan	B
---------------	---

PHOTOGRAPHS

<u>No.</u>		<u>Page</u> <u>No.</u>
1.	Service spillway looking upstream toward the impoundment.	1
2.	Auxiliary spillway outlet channel looking downstream.	1
3.	Bridge approximately 50 feet downstream of the service spillway and 150 feet downstream of the auxiliary spillway.	2
4.	Channel downstream of the bridge which is downstream of the impoundment.	2
5.	Brockton Reservoir Dam spillway approximately 2100 yards upstream of Lower Porter Pond Dam.	3
6.	Waldo Lake Dam spillway about 1050 yards upstream of Lower Porter Pond Dam.	3
7.	Upper Porter Pond Dam spillway approximately 350 yards upstream of Lower Porter Pond Dam.	4
8.	30 Acre Pond Dam spillway about 700 yards downstream of Lower Porter Pond Dam.	4
9.	E. Brett Pond (drained) inlet structure about 1150 yards downstream of Lower Porter Pond Dam.	5
10.	Cross Pond spillway approximately 1450 yards downstream of Lower Porter Pond Dam.	5
11.	Typical reach of Salisbury Brook about 1½ miles downstream of Lower Porter Pond Dam.	6
12.	Entrance to approximately 600 yard long box culvert for Salisbury Brook in Brockton about 1 3/4 miles downstream of Lower Porter Pond Dam.	6

APPENDIX C

PHOTOGRAPHS

DAM NO 137.



Feb 1942



From Commonwealth of Massachusetts DEQE Files

Feb 1942

B-5

COUNTY OF PLYMOUTH, MASSACHUSETTS
ENGINEERING DEPARTMENT
INSPECTION OF DAM AND RESERVOIRS

DAM NO. 137

Inspector *Gfroerer* Date *Feb. 1942* City or Town *Brockton*
Location *Southerly end of Lower Porter's Pond on Field Parkway*
Owner *City of Brockton* Use *(Salisbury Br.)*
Material and Type *Gravel & Clay Dyke - Stone Spillway*

Maximum Head in Feet (Full Pond Level to Bottom of Spillway) *9 feet*
Length *200 feet* Width *10 feet plus*
Area of Watershed *7 Sq. Miles* Capacity *12,000,000* *56 3/4 A.F.* Gallons
Length of Overflow or Spillway *20 feet and 12 feet* Outlets (Pipes or Flumes)
30 inch diam. pipe.

Dam Constructed by *Under Construction by City - W.P.A.* Date *Aug. 1940*
Recent Repairs _____ Date _____

Evidence of Leakage *None*
Condition *New and sound*

Topography of Country Below *Slightly irregular - Salisbury Brook - Ponds - City - Mass.*
Nature, extent, proximity, etc. of buildings, roads or other property in danger if failure should occur
No buildings near. Would be absorbed in 30 Acre Pond.

Remarks and Recommendations *Spillways ample for all conditions except serious failure of dams above.*
Sound & good condition May, 1944. No change Sept. 1946. Good - unchanged May, 1948.
Good - no change Nov. 1950. Sound May 1951. No change - good July 1952. Sound - must water
Feb. 1953. Good - plenty water Dec. 1954. Good as always. Sept. 1956. Good Oct. 1957
Good condition Sept. 1958. Good - no change Oct. 1960. Sound Oct. 1962. Good - no change
Oct. 1964. Good - no change Dec. 1966. Good - no change Oct. 1968. Good - no change
Oct. 1969.

B-4

From Commonwealth of Massachusetts DEQE Files

DESCRIPTION OF DAM

DISTRICT 7

Submitted by A. DUGAN

Dam No. 7-12-44-7

Date 12-5-72

City/Town BROCKTON

Name of Dam LOWER PORTER POND.

1. Location: Topo Sheet No. 32D

Provide 8½" x 11" in clear copy of topo map with location of Dam clearly indicated.

2. Year Built UNKNOWN Year/s of Subsequent Repairs _____

3. Purpose of Dam: Water Supply _____ Recreational X
Irrigation _____ Other _____

4. Drainage Area: 7 Sq.Mi. _____ Acres


5. Normal Ponding Area: _____ Acres _____ Ave. Depth
Impoundment: 12,000,000 Gals. _____ Acre Ft.

6. No. and Type of Dwellings Located Adjacent to Pond or Reservoir
i.e. Summer Homes, etc. NONE

7. Dimensions of Dam: Length 200' Max. Height 9'
Slopes: Upstream Face 5'
Downstream Face 25'
Width Across Top 40'

8. Classification of Dam by Material:
Earth X Conc. Masonry _____ Stone Mason. _____
Timber _____ Rockfill _____ Other _____

From Commonwealth of Massachusetts DEQE Files B-3



U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DIVISION

Contract No. DACW 33-80-C-0014
LOWER PORTER POND DAM

BROCKTON RESERVOIR DAM SYSTEM



DATE: JANUARY 1980
SCALE: 1" = 1000'

B-2

BROCKTON PARK COMMISSION
BROCKTON, MASS.
D.W. FIELD PARK
PLAN

SHOWING AREAS OF PROPOSED
FORESTRY MANAGEMENT

Comp. Gresser & Messer
Consulting Engineers
Boston, Massachusetts

FIG. 3

April, 1968

APPENDIX D

HYDROLOGIC AND HYDRAULIC COMPUTATIONS

SUBJECT	SHEET	BY	DATE	JOB NO
LOWER PORTER POND DAM				

APPENDIX D

HYDROLOGIC & HYDRAULIC COMPUTATIONS

TABLE OF CONTENTS

	<u>PAGE</u>
REGIONAL VICINITY MAP, FIGURE 1, SHOWING FLOOD IMPACT AREA	D-1
T_p COMPUTATIONS	D-2
PMP DATA	D-2
ELEVATION SKETCH OF SPILLWAYS	D-2
STAGE-DISCHARGE & STAGE-STORAGE COMPUTATIONS	D-3
STAGE-DISCHARGE & STAGE-STORAGE GRAPHS	D-4
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWY (BROCKTON DAM)	D-5
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (BROCKTON DAM)	D-6
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWYS. (WALDO LAKE DAM)	D-7
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (WALDO LAKE DAM)	D-8
T_p COMPS., PMP DATA, ELEV. SKETCH DAM & SPWY. (UPPER PORTER DAM)	D-9
STAGE-DISCHARGE & STAGE-STORAGE COMPS. (UPPER PORTER DAM)	D-10
ELEV. SKETCH DAM & SPWYS., STAGE-DISCHARGE & STAGE-STORAGE COMPS. (THIRTY ACRE POND)	D-11
SECTION @ HAZARD AREA	D-12
HEC-1 DAM SAFETY VERSION, COMPUTER OUTPUT	D-13 to D-25
HEC-1 DAM SAFETY VERSION, BREACH ANALYSIS, COMPUTER OUTPUT	D-26 to D-31

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM

SHEET NO D-2 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

LOWER PORTER DAM - H & H

SUBDRAINAGE AREA = 0.08 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$$C_t = 2.0$$

$$C_p = 0.5$$

T_p COMPUTATIONS

$$L = 0.64 \text{ MILES} \quad L_{ca} = 0.23 \text{ MILES}$$

$$T_p = C_t \cdot (L \times L_{ca})^{.3}$$


$$T_p = 2 \times (.64 \times .23)^{.3} \approx \underline{\underline{1.13 \text{ HOURS}}}$$

PMP DATA

FROM HMS #33 THE 24 HOUR 200 sq. mi INDEX RAINFALL IS 21.5

6hr. %	OF INDEX FOR THIS BASIN	= 111
12hr. %	" " " " "	= 124
24hr. %	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



$C = 2.9$ TOP OF DAM

LOOKING DOWNSTREAM

D-2

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB VED-COE, LOWER PORTER POND DAM
SHEET NO D-3 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

LOWER PORTER DAM cont'd

STAGE DISCHARGE

$H = 0$ @ SERVICE SPILLWAY CREST (ELEV. 160.0 MSL)

1) SERVICE SPILLWAY : $C = 3.1$ $L = 12'$ $Z = 1$
 $b_o = 12'$ FOR $H \leq 3$ $Q_1 = C \left(\frac{b_o + b_H}{2} \right) H^{1.5}$
FOR $H > 3$ $Q_1 = C \left[\left(\frac{b_o + b_H}{2} \right) 3^{1.5} + 1.8 \times (H - 3)^{1.5} \right]$

2) AUXILIARY SPILLWAY : $C = 2.7$ $L = 20'$ $Q_2 = CL(H - 0.25)^{1.5}$


3) TOP OF DAM : $C = 2.9$ $L = 200 - 38 = 162'$ $Q_3 = CL(H - 3)^{1.5}$

ELEVATION MSL	H Ft	Q_1 CFS	Q_2 CFS	Q_3 CFS	ΣQ CFS
160	0	0	0	0	0
161	1	40	35	0	75
162	2	123	125	0	248
163	3	242	246	0	488
164	4	297	392	1,339	2,028
165	5	399	559	3,790	4,748
166	6	532	745	6,962	8,239
167	7	688	947	10,718	12,353
168	8	865	1,165	14,979	17,009

STORAGE

	ELEVATION (FT.)	AREA (AC.) (PLANIMETERED FROM USGS)	STORAGE (A.C. FEET) (COMP. BY HEC-1 PROGRAM)
	151	0	0
NORMAL POOL	160	8	24
TOP OF DAM	163	—	54
	170	24	177

STORAGE A-F



LOWER PORTER POND DAM

STAGE VS. STORAGE

STAGE VS. DISCHARGE

APPENDIX D

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COF, LOWER PORTER POND DAM
SHEET NO D-5 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON LAKE DAM - H & H

11

DRAINAGE AREA = 2.8 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$$C_t = 2.0$$

$$C_p = 0.5$$

T_p COMPUTATIONS

$$L = 2.70 \text{ MILES} \quad L_{ca} = 1.40 \text{ MILES}$$

$$T_p = C_t \cdot (L \times L_{ca})^{.3}$$


$$T_p = 2.0 \times (2.7 \times 1.4)^{.3} = \underline{\underline{3.0 \text{ HOURS}}}$$

PMP DATA

FROM HMS #33 THE 24 HOUR 200 sq. mi. INDEX RAINFALL IS 21.5

6hr. %	OF INDEX FOR THIS BASIN	= 111
12hr. %	" " " " "	= 124
24hr. %	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



LOOKING DOWNSTREAM

C = 5.3 w/boards

C = 2.9 TOP OF DAM

C = 2.9 w/out

D-5

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO. D-6 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON LAKE DAM - H&H cont'd

STAGE DISCHARGE WITH FLASHBOARDS

(H = 0 @ SPILLWAY CREST)

1) SPILLWAY : $C = 3.3$ $L = 25'$ $Q_s = CLH^{1.5}$

2) TOP OF DAM : $C = 2.9$ $L = 1800 - 25 = 1775$ $Q_{dam} = CL(H - 3.3)^{1.5}$

ELEVATION MSL	H Ft.	Q_s CFS	Q_{top} CFS	ΣQ CFS
201	0	0	0	0
202	1	83	0	83
203	2	233	0	233
204	3	429	0	429
204.3	3.3	495	0	495
205	4	660	3,015	3,675
206	5	922	11,410	12,332
207	6	1,213	22,637	24,050
208	7	1,528	36,635	38,163
209	8	1,867	52,450	54,317
210	9	2,228	70,050	72,278

SPILLWAY DISCHARGE WITH NO FLASHBOARDS FOR TOP OF DAM EL.

$C = 2.8$ $L = 25$ $Q = CL(H + 2.5)^{1.5}$
 $Q = 978$ CFS

STORAGE

	ELEV. (MSL)	AREA (AC.) (PLANIMETERED FROM USGS)	STORAGE (ACRE FEET) (COMPUTED BY HEC-1 PROGRAM)
	194.3	0	0
NORMAL POOL	201	85	190
TOP OF DAM	204.3	—	493
	210	126	1133

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO D-7 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

WALDO LAKE DAM - H&H

SUBDRAINAGE AREA

= 0.38 sq Mi

SNYDER HYDROGRAPH COEFFICIENTS

$C_t = 2.0$

$C_p = 0.5$

TP COMPUTATIONS

$L = 0.85$ MILES

$L_{ca} = 0.28$

$T_p = C_t \cdot (L \times L_{ca})^{.3}$

$T_p = 2 \times (.85 \times .28)^{.3}$

$T_p \approx \underline{1.25 \text{ HOURS}}$


PMP DATA

FROM HMS #33 THE 24 HOUR 2.00 sq Mi INDEX RAINFALL IS 21.5

6 hr. %	OF INDEX FOR THIS BASIN	= 111
12 hr "	" " " " "	= 124
24 hr "	" " " " "	= 133

DAM ELEVATION & LENGTH and SPILLWAYS DIMENSIONS SKETCH.

LOOKING DOWNSTREAM



LOOKING DOWNSTREAM

D-7

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO. D- 8 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

WALDO LAKE DAM H&H cont'd

STAGE DISCHARGE

$H=0$ @ SPILLWAY CREST

- 1) SERVICE SPILLWAY : $C = 3.1$ $L = 16'$ $Q_1 = CLH^{1.5}$
2) AUXILIARY SPILLWAY : $C = 3.3$ $L = 7.42'$ $Q_2 = CLH^{1.5}$
FOR $H \leq 3.6$
3) $H > 3.6$ PIPE CONTROL $Q_3 = .65AY_2gd^*$
4) TOP OF DAM : $C = 2.9$ $L = 300'$ $Q_4 = CL(H-3.6)^{1.5}$
 $d = \text{depth of water to centroid of pipe}$

ELEVATION MSL	H FT	Q_1	Q_2	Q_3	Q_4	ΣQ
		CFS				
194.5	0	0	0		0	
195.5	1	50	25		0	75
196.5	2	140	69	PIPE FLOW	0	209
197.5	3	258	127		0	418
198.1	3.6	333	160		0	499
198.5	4	397	6	173	936	1,500
199.5	5	555	41	188	6,132	6,916
200.5	6	729	91	202	13,764	14,786
201.5	7	919	154	215	23,209	24,497
202.5	8	1,122	226	227	34,168	35,743

SURCHARGE STORAGE

	ELEVATION (MSL)	AREA (AC)	STORAGE (AC.FEET)
NORMAL POOL (FROM)	194.5	77.	0
TOP OF DAM (TO)	198.1	-	342
	200	137	581

PLANIMETERED
FROM USGS

COMPUTED
BY HEL-1
PROGRAM

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB MED-COE, LOWER PORTER FOND DAM

SHEET NO D-9 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

UPPER PORTER DAM - H & H

11

SUBDRAINAGE AREA

= 0.11 sq. mi

SNYDER HYDROGRAPH COEFFICIENTS

$$C_L = 2.0$$

$$C_P = 0.5$$

T_p COMPUTATIONS

$$L = 0.44 \text{ MILES}$$

$$L_{ca} = 0.22 \text{ MILES}$$

$$T_p = C_L \cdot (L \times L_{ca})^{.3}$$

$$T_p = 2 \times (.44 \times .22)^{.3} \approx \underline{\underline{1.0 \text{ HOUR}}}$$

PMP DATA


FROM HMS #33 THE 24 HOUR 200 sq. mi INDEX RAINFALL IS 21.5

6hr. % OF INDEX FOR THIS BASIN = 111

12hr. % " " " " " = 124

24hr. % " " " " " = 133

DAM ELEVATION & LENGTH and SPILLWAY DIMENSIONS SKETCH



C = 2.8 TOP OF DAM

LOOKING DOWNSTREAM

D-9

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE

SHEET NO D- 10 OF

CALCULATED BY RG DATE

CHECKED BY SHS DATE

SCALE

UPPER PORTER DAM - H & H

STAGE DISCHARGE

(H=0 @ SPILLWAY CREST) ELEVATION = 167.5 MSL

1) SPILLWAY: $C = 3.1$ $L = 25'$ $Q_s = CLH^{1.5}$

2) TOP OF DAM: $C = 2.9$ $L = 340 - 25 = 315$ $Q_{TOP} = CL(H - 3.5)^{1.5}$

ELEVATION MSL	H FT.	Q_s CFS	Q_{TOP} CFS	ΣQ CFS
167.5	0	0	0	
168.5	1	78	0	78
169.5	2	219	0	219
170.5	3	403	0	403
171.0	3.5	508	0	508
172.0	4.5	740	913	1,653
173.0	5.5	1,000	2,584	3,584
174.0	6.5	1,284	4,747	6,031
175.0	7.5	1,592	7,308	8,900
176.0	8.5	1,921	10,213	12,134

STORAGE


	ELEV. (MSL)	AREA (AC) (PLANIMETERED FROM USGS)	STORAGE (AC. FEET) (COMP. BY HEC-1 PROGRAM)
	160	0	0
NORMAL POOL	167.5	11	28
TOP OF DAM	171	19	79

BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER FORTER POND DAM
SHEET NO. D-11 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

THIRTY ACRE POND

DAM ELEVATION & LENGTH and SPILLWAYS DIMENSIONS SKETCH



STAGE DISCHARGE

$H = 0$ @ SERVICE SPILLWAY CREST (ELEV. = 154.0 MSL)

1) SERVICE SPILLWAY FOR $H \leq 3$ $Q_1 = C \left(\frac{b_0 + bH}{2} \right) H^{1.5}$
FOR $H > 3$ $Q_1 = C \left[\left(\frac{b_0 + bH}{2} \right) 3^{1.5} + 12 \times (H-3)^{1.5} \right]$

2) AUXILIARY SPILLWAY $Q_3 = C L (H-1)^{1.5}$

3) TOP OF DAM: $L = 523'$ $Q_4 = C L (H-3)^{1.5}$

ELEVATION MSL	H FT.	Q_1	Q_2	Q_3	Q_4	EQ CFS
154	0	0		0	0	
155	1	23		0	0	23
156	2	75	PIPE FLOW	47	0	122
157	3	11	143	131	0	285
158	4	40	152	242	1517	1951
159	5	112	160	372	4290	4934
160	6	206	168	520	7881	8775

SURCHARGE STORAGE

	ELEVATION	AREA (AC.)	STORAGE (AC FT.)
NORMAL POOL	154	26	0
TOP OF DAM	157	-	86
	160	37	188

PLANIMETERED FROM USGS
COMPUTED BY HEC-1 PROGRAM


BRYANT ASSOCIATES, INC.
648 Beacon Street
BOSTON, MASSACHUSETTS 02215
(617) 247-1800

JOB NED-COE, LOWER PORTER POND DAM
SHEET NO. D-12 OF _____
CALCULATED BY RG DATE _____
CHECKED BY SHS DATE _____
SCALE _____

BROCKTON
DOWNSTREAM ROUTING

SECTION @ HAZARD AREA

1200 FEET DOWNSTREAM OF THIRTYACRE POND DAM



MANNING'S COEFFICIENTS : CHANNEL \rightarrow 0.03
OVERBANKS \rightarrow 0.08

CHANNEL SLOPE : .008 FT./FT.

LOWER FORTER POND DAM BREACH OUTFLOW
ROUTED THROUGH THIRTYAcre POND TO THE DAMAGE AREA

INPUT

HYDROLOGIC ANALYSIS OF LOWER POWER-POND
NATIONAL DAM SAFETY PROGRAM
NEW ENGLAND DIVISION - CORPS OF ENGINEERS

— 1 —

—

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

1
OUTFLOW FROM LOWER POWER POND

— — — — —

1	162	164	145	-163
	162	164	145	-144

5-209-202A-748-0239

24
270
—
300

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

1	150	163.0	163.0
---	-----	-------	-------

OWTEN POND HNEACH THROUGH THIRTYACRE POND

[illegible]

157	159	160
-----	-----	-----

122	285	1951	4934	8775
-----	-----	------	------	------

— 2 —

1. *Journal of the American Medical Association*, 1997; 277: 1001-1005.

0

ROUTING TO HAZARD CENTER

—

[illegible]

555	051	0032	591	0021	0
555	051	0032	591	0021	0

2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841

1000

1. The first step in the process of creating a new product is to identify a market need. This involves conducting market research to determine what consumers are looking for and what gaps exist in the current market. Once a need is identified, the next step is to develop a concept that addresses this need. This is often done through brainstorming sessions with a team of designers and engineers. The concept is then refined through prototyping and testing, ensuring that it meets the requirements of the target market. Finally, the product is manufactured and distributed to consumers, with ongoing monitoring to ensure its success in the market.

100

100

REPRODUCED AT GOVERNMENT EXPENSE

FLOOD RESULTS AT LOWER
PORTER POND DAM

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1									
ELEVATION STORAGE OUTFLOW		INITIAL VALUE		SPILLWAY CREST		TOP OF DAM			
24. 0.		160.00		160.00		163.00		54. 488.	
								SPILLWAY DISCHARGE CAPACITY	
RATIO OF PMF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS		
.10	161.38	0.00	36.	140.	0.00	31.67	0.00		
.20	162.41	0.00	47.	345.	0.00	29.50	0.00		
.30	163.20	.20	56.	799.	7.17	22.83	0.00		
.40	163.76	.76	63.	1663.	10.67	20.83	0.00		
.50	164.18	1.18	69.	2505.	12.67	19.83	0.00		
.60	164.43	1.43	72.	3195.	14.00	19.33	0.00		
.70	164.65	1.65	75.	3809.	15.17	19.17	0.00		
.80	164.87	1.87	78.	4381.	16.00	19.00	0.00		
1.00	165.23	2.23	84.	5554.	17.33	18.83	0.00		
				TEST FLOOD ELEVATION		TEST FLOOD ROUTED OUTFLOW			

FLOOD RESULTS AT BROCKTON RESERVOIR DAM

SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE SPILLWAY CREST TOP OF DAM
201.00 201.00 204.30
190. 190. 493.
0. 0. 495.

ELEVATION
STORAGE
OUTFLOW

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	202.93	0.00	353.	208.	0.00	23.00	0.00
.20	204.22	0.00	478.	478.	0.00	22.33	0.00
.30	204.47	.17	511.	1245.	5.50	19.57	0.00
.40	204.59	.29	523.	1826.	7.67	19.00	0.00
.50	204.70	.40	533.	2302.	9.33	18.83	0.00
.60	204.80	.50	543.	2765.	10.33	18.83	0.00
.70	204.90	.60	554.	3226.	11.33	18.83	0.00
.80	205.00	.70	564.	3694.	12.17	18.83	0.00
.90	205.11	.81	575.	4639.	13.50	18.67	0.00
1.00							

FLOOD RESULTS AT WATER LAKE DAM

SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE SPILLWAY CREST TOP OF DAM
194.50 194.50 198.10
0. 0. 342.
0. 0. 499.

ELEVATION
STORAGE
OUTFLOW

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	195.00	0.00	126.	142.	0.00	29.67	0.00
.20	197.18	0.00	242.	351.	0.00	27.67	0.00
.30	198.22	.12	356.	804.	4.33	22.33	0.00
.40	198.51	.43	393.	1674.	7.50	20.50	0.00
.50	198.67	.57	410.	2445.	9.50	19.50	0.00
.60	198.79	.69	424.	3081.	10.67	19.17	0.00
.70	198.90	.80	437.	3644.	11.83	19.00	0.00
.80	198.99	.89	442.	4179.	12.67	19.00	0.00
.90	199.00	.90	445.	5285.	14.00	18.83	0.00
1.00							

FLOOD RESULTS AT UPPER PORTER POND DAM

SUMMARY OF DAM SAFETY ANALYSIS

INITIAL VALUE SPILLWAY CREST TOP OF DAM
167.50 167.50 171.00
24. 28. 79.
0. 0. 508.

ELEVATION
STORAGE
OUTFLOW

RATIO OF P.F.	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.10	168.94	0.00	46.	141.	0.00	30.83	0.00
.20	170.20	0.00	65.	347.	0.00	28.83	0.00
.30	171.25	.24	84.	794.	3.83	22.67	0.00
.40	172.00	1.00	109.	1653.	7.33	20.67	0.00
.50	172.41	1.43	119.	2476.	9.17	19.67	0.00
.60	172.77	1.77	117.	3144.	10.50	19.33	0.00
.70	173.06	2.06	124.	3738.	11.67	19.00	0.00
.80	173.29	2.29	130.	4237.	12.50	19.00	0.00
.90	173.70	2.76	142.	4441.	14.00	18.83	0.00
1.00							

D-24

PEAK FLOW AND STORAGE (END OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOWS IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOWS									
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9	RATIO 10
HYDROGRAPH AT BROCKTON	2.40	7.25	1	465.	931.	1396.	1862.	2327.	2792.	3258.	3723.	4654.	4654.
ROUTED TO DAM 0	2.40	7.25	1	204.	478.	1245.	1826.	2302.	2765.	3226.	3694.	4639.	4639.
HYDROGRAPH AT WALDO	3.14	9.81	1	102.	204.	307.	409.	511.	613.	715.	817.	1022.	1022.
2 COMBINED	5.54	17.06	1	217.	434.	651.	868.	1073.	1278.	1483.	1688.	2126.	2126.
ROUTED TO WALDO	3.14	9.81	1	142.	284.	426.	568.	710.	852.	994.	1136.	1416.	1416.
HYDROGRAPH AT PORTER	3.14	9.81	1	33.	67.	100.	133.	166.	200.	233.	266.	333.	333.
2 COMBINED	6.28	19.62	1	175.	350.	525.	699.	874.	1049.	1224.	1399.	1749.	1749.
ROUTED TO PORTER	3.14	9.81	1	141.	282.	423.	564.	705.	846.	987.	1128.	1411.	1411.
HYDROGRAPH AT PORTER	3.14	9.81	1	24.	48.	72.	96.	120.	144.	168.	192.	240.	240.
2 COMBINED	6.28	19.62	1	165.	330.	495.	660.	825.	990.	1155.	1320.	1651.	1651.
ROUTED TO PORTER	3.14	9.81	1	141.	282.	423.	564.	705.	846.	987.	1128.	1411.	1411.
HYDROGRAPH AT PORTER	3.14	9.81	1	24.	48.	72.	96.	120.	144.	168.	192.	240.	240.
2 COMBINED	6.28	19.62	1	165.	330.	495.	660.	825.	990.	1155.	1320.	1651.	1651.
ROUTED TO PORTER	3.14	9.81	1	141.	282.	423.	564.	705.	846.	987.	1128.	1411.	1411.

TEST FLOOD PEAK INFLOW

ROUTED TEST FLOOD OUTFLOW

ROUTED OUTFLOW FROM LOWEN PORTER POND

STAGE	MSIPS 1	MSFUL D	LAG	ANSKK 0	4 0.000	TSK 0.000	STORA -100.	ISPRAY -1
160.00	161.00	162.00	163.00	164.00	165.00	166.00	167.00	168.00
75.00	248.00	48A.00	2024.00	4748.00	12353.00	17009.00	194.00	194.00

DATA FOR
POND DAM
STATE-DISCHARGE
LOWER PORTER

STAGE-STORAGE DATA FOR
LOWER PORTER POND DAM

SPILLWAY CREST ELEVATION → 1

TOP OF DAM ELEVATION -

0.1 PMF

YEAR OUTFLOW IS 140. AT TIME 31.67 HOURS.

2 Amf

YEAR 507000 IS 345. AT TIME 29.50 HOURS

James

4 PMF

١٥٠

.5 pf

300,000

6/7/41
EAM OUTFLOW IS 3195. AT TIME 19.33 HOURS

7 PMF

YEAR JULY 15 3409. AT TIME 19.17 HOURS

368

EAR OUTCOME IS 4381. AT TIME 19.00 HOURS
PWC

111

ROUTED OUTFLOWS FROM
LOWER PORTER POND DAM

TEST FLOOD

LOCAL RUNOFF TO LOWER PORTER POND

SUB-AREA RUNOFF COMPUTATION

INFLU TO LOWER PORTER POND LESS UPPER PORTER POND													
ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO					
LPRT	0	0	0	0	0	1	0	0					
HYDROGRAPH DATA													
LYNG	LONG	TAREA	SNAP	TRSDA	TRSPC	RATIO	ISNOW	ISAME	LOCAL				
1	1	.08	0.00	3.37	0.00	0.000	0	1	0				
PRECIP DATA													
SPEE	PMS	R6	R12	R24	R48	R72	R96						
0.00	21.50	111.00	124.00	133.00	0.00	0.00	0.00						
LOSS DATA													
LPRT	STIRK	ULTRK	RTIOL	ERAIN	STIRKS	RTIOL	STIRL	CNSTL	ALSMX	RTIMP			
0	0.00	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00			
UNIT HYDROGRAPH DATA													
TP= 1.00 CP= .50 NTA= 0													
RECESSION DATA													
STINTU= -1.70 ORCSN= -.10 RTIOR= 2.00													
UNIT HYDROGRAPH 16 END-OF-PERIOD ORDNATES, LAG= 1.00 HOURS, CP= .50 VOL= 1.00													
2.	6.	11.	18.	23.	26.	26.	23.	21.	18.				
16.	14.	13.	11.	10.	9.	8.	7.	6.	5.				
5.	4.	3.	3.	3.	2.	2.	2.	2.	1.				
1.	1.	1.	1.	1.	1.	1.	1.	1.	0.				
0.	0.	0.	0.	0.	0.	0.	0.	0.	0.				
END-OF-PERIOD FLOW													
MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q	MO,DA	HR,MIN	PERIOD	RAIN	EXCS	LOSS	COMP Q
0													
SUM 22.08 21.68 1.20 6748.													
(581.) (551.) (30.) (191.08)													
COMBINE HYDROGRAPHS													
COMBINING LOWER PORTER POND LOCAL RUNOFF AND UPPER PORTER POND ROUTED OUTFLOW													
ISTAU	ICOMP	IECON	ITAPE	JPLT	JPRI	INAME	ISTAGE	IAUTO					
TOTAL	2	0	0	0	0	1	0	0					

0 - 21

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM UPPER PORTER POND

ISTAG	ICOMP	TECON	ITAPE	JPLT	JGRT	INAME	ISTAGE	IAUTO
UPHRT	1	0	0	0	0	1	0	0
ROUTING DATA								
CEUSS	CLOSS	AVG	THES	ISAME	IOPT	IPMP	LSTH	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS NSTUL LAG ANSKK X TSK STORA TSPRAY								
1	0	0	0.000	0.000	0.000	-168.	-1	

STAGE	167.50	168.50	169.50	170.50	171.00	172.00	173.00	174.00	175.00	176.00
FLOW	0.00	78.00	219.00	403.00	508.00	1653.00	3584.00	6031.00	8900.00	12134.00

STAGE-STORAGE DATA
FOR UPPER PORTER POND DAM

SURFACE AREA	0.	11.	19.
--------------	----	-----	-----

CAPACITY	0.	28.	79.
----------	----	-----	-----

ELEVATION	160.	168.	171.
-----------	------	------	------

SILLWAY CREST ELEVATION → 167.5 CHSL SP=10 COOL EXPW ELEV COOL CAHEA EXPL

DAM DATA
TOPEL COOLD EXPO DAMWID

→ 171.0 0.0 0.0 0.

.1 PMF	TOP OF DAM ELEVATION	→ 171.0	0.0	0.0	0.
PEAK OUTFLOW IS	141.	AT TIME	30.83	HOURS	
.2 PMF					
PEAK OUTFLOW IS	367.	AT TIME	28.83	HOURS	
.3 PMF					
PEAK OUTFLOW IS	798.	AT TIME	22.07	HOURS	
.4 PMF					
PEAK OUTFLOW IS	1653.	AT TIME	20.67	HOURS	
.5 PMF					
PEAK OUTFLOW IS	2476.	AT TIME	19.67	HOURS	
.6 PMF					
PEAK OUTFLOW IS	3164.	AT TIME	19.33	HOURS	
.7 PMF					
PEAK OUTFLOW IS	3739.	AT TIME	19.00	HOURS	
.8 PMF					
PEAK OUTFLOW IS	4297.	AT TIME	19.00	HOURS	
PMF					
PEAK OUTFLOW IS	5441.	AT TIME	18.83	HOURS	

ROUTED OUTFLOWS FROM
UPPER PORTER POND

LOCAL RUNOFF TO UPPER PORTER POND

SUB-AREA RUNOFF COMPUTATION

INFLOW TO UPPER PORTER POND LESS WALDO LAKE

ISTAO	ICOMP	IECON	ITAPE	JPLY	JPRI	INAME	ISTAGE	IAUTO
UPORT	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

SNAP	IRSDA	IRSPC	RATIO	ISNOW	ISAME	LOCAL
0.00	0.00	3.37	0.00	0.00	1	0

PRECIP DATA

R6	R12	R24	R48	R72	R96
0.00	21.50	111.00	124.00	133.00	0.00

THSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LRPT	STNKH	RTIOL	ERAIN	STRKS	RTIOK	SIRTL	CNSTL	ALSMX	RTIMP
0	0.00	0.00	1.00	0.00	1.00	0.00	.05	0.00	0.00

UNIT HYDROGRAPH DATA

TP= 1.00 CP= .50 NTA= 0

RECESSION DATA

STRTD= -1.70 MRESN= -.10 RTIOR= 2.00

UNIT HYDROGRAPH 46 END-OF-PERIOD ORIGINATES. LAG= 1.00 HOURS, CP= .50 VOL= 1.00

2.	8.	16.	24.	31.	35.	32.	28.	25.
22.	20.	17.	15.	13.	12.	10.	9.	8.
6.	6.	5.	4.	4.	3.	3.	3.	2.
2.	2.	1.	1.	1.	1.	1.	1.	1.
1.	0.	0.	0.	0.	0.	0.	0.	0.

END-OF-PERIOD FLOW

MO.DA	HR.MM	PERIOD	RAIN	EACS	LOSS	COMP Q	MO.DA	HR.MM	PERIOD	RAIN	EACS	LOSS	COMP Q
<p>SUM 22.89 21.68 1.20 9280. (581.1) (551.1) (30.1) (262.78)</p>													

COMBINE HYDROGRAPHS

COMBINE HYDROGRAPHS - COMBINING UPPER PORTER POND LOCAL RUNOFF AND WALDO LAKE RATED OUTFLOW

ISTAO	ICOMP	IECON	ITAPE	JPLY	JPRI	INAME	ISTAGE	IAUTO
TOTAL	2	0	0	0	0	1	0	0

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM WALDO LAKE

ISTAO ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
WALDO 1 0 0 0 0 0 0 0

ROUTING DATA
QLOSS CLOSS AVG IRES ISAME IOPT IPMP LSTR
0.0 0.000 0.00 1 1 0 0 0

NSTPS NSTOL LAG ANSKK X TSK STORA ISPRAT
1 0 0 0.000 0.000 0.000 -195. -1

STAGE 194.50 195.50 196.50 197.50 198.10 198.50 199.50 200.50 201.50 202.50 } STAGE - DISCHARGE DATA
FLOW 0.00 75.00 209.00 418.00 499.00 1500.00 6916.00 24497.00 35743.00 } FOR WALDO LAKE DAM

SURFACE AREA 77. 137. } STAGE-STORAGE DATA
CAPACITY 581. }
ELEVATION 195. 200. } FOR WALDO LAKE DAM

SPILLWAY CREST ELEVATION → 194.5 CHEL SPWID CDDW EXPW ELEV COOL CAREN EXPL
→ 194.5 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA

TOPEL CDDW EXPW DAMDID
→ 198.1 0.0 0.0 0.

1 PMF TOP OF DAM ELEVATION → 198.1
PEAK OUTFLOW IS 142. AT TIME 29.07 HOURS

2 PMF
PEAK OUTFLOW IS 351. AT TIME 27.67 HOURS

3 PMF
PEAK OUTFLOW IS 804. AT TIME 22.33 HOURS

4 PMF
PEAK OUTFLOW IS 1674. AT TIME 20.50 HOURS

5 PMF
PEAK OUTFLOW IS 2445. AT TIME 19.50 HOURS

6 PMF
PEAK OUTFLOW IS 3081. AT TIME 19.17 HOURS

7 PMF
PEAK OUTFLOW IS 3644. AT TIME 19.00 HOURS

ROUTED OUTFLOWS
FROM WALDO LAKE

8 PMF
PEAK OUTFLOW IS 4179. AT TIME 19.00 HOURS

PMF
PEAK OUTFLOW IS 5245. AT TIME 18.41 HOURS

LOCAL RUNOFF TO WALDO LAKE

SUB-AREA RUNOFF COMPUTATION

INFLOW TO WALDO LAKE LESS BROCKTON

ISTAD ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUO

HYDROGRAPH DATA

INVOG IORG IAREA SNAP IASDA TRSPC RATIO TSNOV TSAME LOCAL

PRECIP DATA

SPFE PMS R6 R12 R24 R48 R72 R96

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT STPKR ULTKR HTLOC ERAIN STRKS HTLOK STRIL CNSYL ALSHX RTIMP

UNIT HYDROGRAPH DATA

TP= 1.25 CP= .50 NTA= 0

RECESSION DATA

STARTO= -1.70 GRCSN= -.10 RTION= 2.00

UNIT HYDROGRAPH 59 END-OF-PERIOD ORIGINATES. LAQ= 1.26 HOURS. CP= .50 VOL= 1.00

4.	16.	32.	50.	69.	85.	95.	95.	86.
78.	71.	64.	58.	53.	48.	39.	36.	32.
24.	27.	24.	22.	20.	18.	15.	13.	12.
11.	10.	9.	8.	7.	6.	6.	5.	5.
4.	4.	3.	3.	3.	2.	2.	2.	2.
2.	1.	1.	1.	1.	1.	1.	1.	1.

END-OF-PERIOD FLOW

MO.DA HR.MN PERIOD RAIN EXCS LOSS COMPO MO.DA HR.MN PERIOD RAIN EXCS LOSS COMPO

SUM 22.MR 21.68 1.20 319MS.
(581.1(551.1(30.1(905.71)

D-17

COMBINE HYDROGRAPHS - COMBINING WALDO LAKE LOCAL RUNOFF AND BROCKTON RESERVOIR ROUTED OUTFLOW

COMBINE HYDROGRAPHS

ISTAD ICOMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUO

TAL

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM BROCKTON LAKE DAM

ISTAU	ICOMP	IECON	ITAPE	JPLT	JPHT	INAME	ISTAGE	IAUTO
DAM 0	1	0	0	0	0	1	0	0
QLOSS	CLOSS	AVG	IRIS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSTPS	NSTOL	LAG	AMSKK	X	TSK	STORA	ISPRAT	
1	0	0	0.000	0.000	0.000	-201.	-1	
STAGE	201.00	202.00	203.00	204.00	204.30	205.00	206.00	207.00
	210.00							
FLOW	0.00	83.00	233.00	429.00	495.00	3675.00	12332.00	24050.00
	70278.00							
SURFACE AREA	0.	85.	126.					
CAPACITY	0.	190.	1133.					
ELEVATION	194.	201.	210.					

STAGE-STORAGE DATA FOR BROCKTON RESERVOIR DAM

CRSL	SPW10	COOW	EXPV	ELEVEL	COUL	CAREA	EXPL
→ 201.0	0.0	0.0	0.0	0.0	0.0	0.0	0.0
TOPEL	COOW	EXPD	DAMWID				
→ 204.3	0.0	0.0	0.0				

SPILLWAY CREST ELEVATION → 201.0

TOP OF DAM ELEVATION → 204.3

PEAK OUTFLOW IS	208. AT TIME 23.00 HOURS
.1 PMF	
PEAK OUTFLOW IS	478. AT TIME 22.33 HOURS
.2 PMF	
PEAK OUTFLOW IS	1285. AT TIME 19.67 HOURS
.3 PMF	
PEAK OUTFLOW IS	1826. AT TIME 19.00 HOURS
.4 PMF	
PEAK OUTFLOW IS	2302. AT TIME 18.83 HOURS
.5 PMF	

ROUTED OUTFLOWS FROM BROCKTON RESERVOIR

.6 PMF	PEAK OUTFLOW IS 2765. AT TIME 18.83 HOURS
.7 PMF	PEAK OUTFLOW IS 3226. AT TIME 18.33 HOURS
.8 PMF	PEAK OUTFLOW IS 3696. AT TIME 18.83 HOURS
.9 PMF	PEAK OUTFLOW IS 4430. AT TIME 18.67 HOURS

.....
 LOND JOMAY PAGE -11
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATE 02/11/80.
 TIME 0 14.45.16.

HYDROLOGIC ANALYSIS OF LOWER PORTER POND
 NATIONAL DAM SAFETY PROGRAM
 NEW ENGLAND DIVISION - CORPS OF ENGINEERS

NO	NHR	NMIN	IDAY	JOPEH	NMT	LROPT	TRACE	IPLT	IPRT	INSTAN
300	0	10	0	5	0	0	0	0	-4	0

MULTI-PLAN ANALYSES TO BE PERFORMED

PERCENTAGES OF PMF USED → RTIOS= .10 .20 .30 .40 .50 .60 .70 .80 1.00

INFLOW HYDROGRAPH DEVELOPMENT FOR BROCKTON RESERVOIR

SUB-AREA RINOFF COMPUTATION

INFLOW TO BROCKTON LAKE

ISIAO	ICOMP	IECON	ITAPE	JPLT	JPRT	INAME	ISTAGE	IAUTO
BROCK	0	0	0	0	0	1	0	0

IRYOS	IRYOS	IRYOS	IRYOS	IRYOS	IRYOS	IRYOS	IRYOS	IRYOS
1	1	2.80	0.00	3.37	0.00	0.000	0	1

SPFE	PMS	R12	R24	R48	R72	R96
0.00	21.50	111.00	124.00	133.00	0.00	0.00

TRSPC COMPUTED BY THE PROGRAM IS .800

LOSS DATA

LROPT	STARR	ULTRA	WTOL	ERAIN	STARR	RTIOX	STYCL	CNSTL	ALSKA	RTIMP
0	0.00	1.00	0.00	0.00	1.00	0.00	.05	0.00	0.00	0.00

UNIT HYDROGRAPH DATA

1P= 3.00 CP= .50 NTA= 0

RECESSION DATA

STARCE= -1.70 UNCSN= -.10 RTION= 2.00

UNIT HYDROGRAPH TO END-OF-PERIOD ORIGINATES. LAG= 2.99 HOURS CP= .50 VOL= .98

4.	14.	30.	48.	69.	91.	115.	141.	167.	194.
220.	243.	263.	279.	293.	303.	310.	313.	309.	299.
287.	276.	265.	254.	244.	234.	224.	215.	207.	198.
190.	183.	175.	168.	162.	155.	149.	143.	137.	132.
126.	121.	116.	112.	107.	103.	99.	95.	91.	87.

84.	59.	37.	24.	16.	84.	59.	37.	24.	16.
84.	80.	77.	74.	71.	68.	65.	63.	60.	58.
55.	53.	51.	49.	47.	45.	43.	42.	40.	38.
37.	35.	34.	32.	31.	30.	29.	28.	26.	25.
24.	23.	22.	21.	20.	19.	18.	17.	16.	15.
16.	15.	14.	13.	12.	11.	10.	9.	8.	7.

MO.DA HR.MM PERIOD MAIN EACS LOSS MO.DA HR.MM PERIOD MAIN EACS LOSS COMP H

[illegible]

RUNOFF HYDROGRAPH AT	HROCK
ROUTE HYDROGRAPH TO	DAM 0
RUNOFF HYDROGRAPH AT	WALDOO
COMBINE 2 HYDROGRAPHS AT TOTAL	
ROUTE HYDROGRAPH TO	WALDOO
RUNOFF HYDROGRAPH AT	UPOUT
COMBINE 2 HYDROGRAPHS AT TOTAL	
ROUTE HYDROGRAPH TO	UPOUT
RUNOFF HYDROGRAPH AT	LPORT
COMBINE 2 HYDROGRAPHS AT TOTAL	
ROUTE HYDROGRAPH TO	LPORT
END OF NETWORK	

FLOODS ROUTED THROUGH LOWER PORTER POND DAM WITHOUT BREACHING

.....
FLOOD HYDROGRAPH PACKAGE (HEC-1)
DAM SAFETY VERSION JULY 1978
LAST MODIFICATION 26 FEB 79
.....

INPUT

HYDROLOGIC ANALYSIS OF LOWER PORTER POND									
NATIONAL DAM SAFETY PROGRAM									
NEW ENGLAND DIVISION - COMPS OF ENGINEERS									
1	A								
2	A								
3	A								
4	B	300	0	0	0	0	0	-4	0
5	B	5							
6	J	1	9	1					
7	J	1	2	3	.4	.5	.6	.7	1.0
8	K	0	BRUCK						
9	K	0	INFLW TO BRUCKTON LAKE						
10	M	1	1	2.8	0	3.37			1
11	P	0	21.5	111	124	133			
12	T						0	.05	
13	V	3.0	0.5						
14	X	-1.7	-0.1	2					
15	K	1	DAM 0						
16	K	1	ROUTED OUTFLOW FROM BRUCKTON LAKE DAM						
17	Y				1	1			
18	Y	1							
19	Y	201	202	203	204	204.3	205	-201.0	-1
20	Y	210						206	207
21	Y	0	83	233	429	495	3675	12332	24050
22	Y	70278							38163
23	Y	0	85	126					54317
24	Y	194.3	201	210					
25	Y	201							
26	Y	204.3							
27	K	0	WALDO						
28	K	1	INFLW TO WALDO LAKE LESS BRUCKTON						
29	M	1	1	0.38	3.37				
30	P	0	21.5	111	124	133			1
31	T						0.0	0.05	
32	V	1.25	0.5						
33	X	-1.7	-0.1	2					
34	K	2	TOTAL						
35	K	1	COMBINE HYDROGRAPHS						
36	K	1	WALDO						
37	K	1	ROUTED OUTFLOW FROM WALL LAKE						
38	Y				1	1			
39	Y	1							
40	Y	194.5	195.5	196.5	197.5	198.1	198.5	-194.5	-1
41	Y	0	75	209	418	499	1500	199.5	200.5
42	Y	77	137					6916	14786
43	Y	194.5	200					24497	202.5
44	Y	194.5						35743	
45	Y	194.1							
46	K	0	UPPER						
47	K	1	INFLW TO UPPER PORTER POND LESS WALDO LAKE						
48	M	1	1	0.11	0	3.37			1
49	P	0	21.5	111	124	133			
50	T						0.0	0.05	

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAM SAFETY VERSION JULY 1978
 LAST MODIFICATION 26 FEB 79

RUN DATED 02/12/80.
 TIMES 10.36.59.

HYDROLOGIC ANALYSIS OF LOWER PORTER POND
 NATIONAL DAM SAFETY PROGRAM
 NEW ENGLAND DIVISION - CORPS OF ENGINEERS

JOB SPECIFICATION
 NO NHP NMN IUAY IHR IMIN METRC IPLT IPRT NSTAN
 300 0 10 0 0 0 0 0 0 0 0
 JOPER NAT LROPT TRACE
 5 0 0 0

MULTI-PLAN ANALYSES TO BE PERFORMED
 NPLAN=1 NRTIO=1 LRTIO=1

NO INFLOW → RTIOS= 0.00

.....

HYDROGRAPH ROUTING

ROUTED OUTFLOW FROM LOWER PORTER POND

ISTAD ICUMP IECON ITAPE JPLT JPRT INAME ISTAGE IAUTO
 0 0 0 0 0 0 0 0 0
 ROUTING DATA
 QLOSS CLOSS AVG IHES ISAME IOPT IPMP LSTR
 0.0 0.000 0.00 1 1 0 0 0
 NSTPS NSTUL LAG ANSKK X ISK STORA ISPRAT
 1 0 0 0.000 0.000 0.000 -163.0

STAGE 150.00 161.00 162.00 163.00 164.00 165.00 166.00 167.00 168.00 } STAGE-DISCHARGE DATA FOR
 FLOW 0.00 75.00 248.00 488.00 2028.00 4748.00 8239.00 12353.00 17009.00 } LOWER PORTER POND DAM

SURFACE AREA= 0.0 AC

CAPACITY= 0.0 24.0 177.0 } STAGE-STORAGE DATA FOR
 ELEVATION= 151.0 160.0 170.0 } LOWER PORTER POND DAM

SPILLWAY CREST ELEVATION → 160.0 CMEL SPWID CUWV EXPV ELEV COUL CAREN EXPL
 0.0 0.0 0.0 0.0 0.0 0.0 0.0 0.0

DAM DATA
 TOP OF DAM ELEVATION → 163.0 TOPEL COUD EXPO DAMWID
 20.0 159.00 1.00 0.0 0.0

D-27

DAM BREACH DATA
 Z ELRM IFAIL WSEL FATEL } BREACH DATA - FAILURE BEGINS IMMEDIATELY
 20.0 159.00 1.00 163.00 163.00 } WITH RESERVOIR SURFACE AT TOP OF DAM

HEADING DAM FAILURE AT 0.00 HOURS → PEAK BREACH DISCHARGE

PEAK DISCHARGE IS 177.0 CFS AT TIME 0.00 HOURS

HYDROGRAPH ROUTING

LOWER PORTER POND BREACH THROUGH THIRTYACRE POND

ISFAD	ICOMP	IECON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
TPOND	1	0	0	0	0	1	0	0
ROUTING DATA								
GLSS	CLSS	AVG	IRFS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSIPS								
1	0	0	0.000	0.000	0.000	0.000	-154.	-1

STAGE 154.00 155.00 156.00 157.00 158.00 159.00 160.00 } STAGE-DISCHARGE DATA FOR THIRTYACRE POND DAM

FLOW 0.00 23.00 122.00 285.00 1951.00 4934.00 8775.00

SURFACE AREA= 26. 37. } STAGE-STORAGE DATA

CAPACITY= 0. 188. } FOR THIRTYACRE POND DAM

ELEVATION= 154. 160.

SPILLWAY CREST ELEVATION → 154.0 CREL SPWID COOM EXPW ELEV COOL CAHEA EXPL

TOP OF DAM ELEVATION → 157.0 TOPEL COUD EXPD DAMWID

PEAK OUTFLOW IS 71. AT TIME 1.83 HOURS

ROUTED OUTFLOW AT THIRTYACRE POND DAM DUE TO BREACH OF LOWER PORTER POND DAM

HYDROGRAPH ROUTING

CHANNEL ROUTING TO HAZARD CENTER

ISFAD	ICOMP	IECON	ITAPE	JPLT	JPRF	INAME	ISTAGE	IAUTO
HAZARD	1	0	0	0	0	1	0	0
ROUTING DATA								
GLSS	CLSS	AVG	IRFS	ISAME	IOPT	IPMP	LSTR	
0.0	0.000	0.00	1	1	0	0	0	
NSIPS								
1	0	0	0.000	0.000	0.000	0.000	-1.	0

NORMAL DEPTH CHANNEL ROUTING

QV(1) QV(2) QV(3) ELNVT ELMAX RLNTH SEL } CHANNEL CHARACTERISTICS AT
 .0000 .0300 .0600 138.0 150.0 1200. .00800 } DOWNSTREAM DAMAGE AREA

CHANNEL INVERT ELEVATION

CROSS SECTION COORDINATES--STA+ELEV+STA+ELEV--ETC
 0.00 150.00 540.00 140.00 543.00 138.00 555.00 138.00 558.00 140.00 } CHANNEL CROSS-SECTION AT
 1100.00 140.00 1700.00 145.00 2300.00 150.00 } DOWNSTREAM DAMAGE AREA

STORAGE	0.00	112.05	135.81	.23	.48	161.49	189.08	.77	9.61	21.90	36.11	52.22	70.25	90.19
														394.77
OUTFLOW	0.00	33745.64	25.09	80.84	161.54	1004.34	3526.43	7268.17	12147.89	18133.02	25212.25	318.56	355.70	
			42660.04	53046.06	64559.63	77215.15	91030.89	106025.57	122218.70	139430.39	158281.17			
STAGE	138.00	138.61	139.26	140.53	141.16	141.79	142.42	143.05	143.68					
	144.32	144.95	145.58	146.21	146.84	147.47	148.11	148.74	149.37					
FLOW	0.00	25.09	80.84	161.54	1004.34	3526.43	7268.17	12147.89	18133.02	25212.25				
	33385.64	42660.04	53046.06	64559.63	77215.15	91030.89	106025.57	122218.70	139430.39	158281.17				

MAXIMUM STAGE IS 139.1 → STREAM ELEVATION AT DAMAGE CENTER

.....

PRINTED IN U.S.A.

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE	
163.00	
54.	
489.	

SPILLWAY CREST
160.00
24.
0.

TOP OF DAM
163.00
54.
488.

RATIO OF INF	MAXIMUM RESERVOIR W.S. ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
0.00	162.93	0.00	54.	489.	0.00	0.00	0.00

PEAK OUTFLOW DURING BREACHING

THIRTYACRE POND DAM

D-31

APPENDIX E

INFORMATION AS CONTAINED IN THE NATIONAL INVENTORY OF DAMS

12-54
FEMA

INVENTORY OF DAMS IN THE UNITED STATES

IDENTITY NUMBER	DIVISION	STATE	COUNTY	CONGRESS DIST.	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
MA 426 NED	MA 023 1				LOWER PORTER POND DAM	4205.0	7102.6	04 JAN 80

POPULAR NAME	NAME OF IMPONDMENT			
	LOWER PORTER POND			
REGION BASIN	RIVER OR STREAM	NEAREST DOWNSTREAM CITY - TOWN - VILLAGE	DIST FROM DAM (MI.)	POPULATION
01 06	BEAVER BROOK	BROCKTON	0	90000

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STRUCTURAL HEIGHT (FT.)	HYDRAULIC HEIGHT (FT.)	IMPOUNDING CAPACITIES
REGG	1932	R	12	12	MAXIMUM NORMAL
					54
					24

DIST OWN FED R PHV/FED 8C8 A VER/DATE
NED N N N : N

REMARKS

D/S HAS	SPILLWAY LENGTH (FT.)	MAXIMUM DISCHARGE (CY)	VOLUME OF DAM (CY)	POWER CAPACITY (MW)	INSTALLED PROPOSED	NO. LENGTH WIDTH	NAVIGATION LOCKS
2	200 U 32	448	750				

OWNER	ENGINEERING BY	CONSTRUCTION BY
BROCKTON DEPT. PARKS & REC.	UNKNOWN	WORK PROJECTS ADMIN.

DESIGN	CONSTRUCTION	OPERATION	MAINTENANCE
NONE	NONE	MA DEDE	MA DEDE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
O'BRIEN & GERE ENGINEERS INC.	17 OCT 79	PL 92-367

REMARKS
COMBINED SERVICE & AUX. SPILLWAY LENGTHS AT SAME CREST ELEV.

END

FILMED

7-85

DTIC